## REMEDIAL INVESTIGATION, RISK ASSESSMENT AND CLEANUP PLAN BETHLEHEM WORKS SITE BETHLEHEM, PENNSYLVANIA

Volume 1

SAIC Project 01-1408-05-7874-501

Prepared for

Bethlehem Steel Corporation Bethlehem, Pennsylvania

Prepared by

R.E. Wright Environmental, Inc. 3240 Schoolhouse Road Middletown, PA 17057 (717) 944-5501

May 28, 1998

Respectfully submitted,

Brett W. Cox, P.G. **Project Director** 



Charles D. Campbell

Charles D. Campbell

Risk Assessor

## TABLE OF CONTENTS

(Revised August 27, 1998)

		·	Page
EX	ECUTIVE SU	MMARY	1
1.0	INTRODU	CTION	5
	1.1	Assumptions	
	1.2	Document Organization	8
2.0	SITE DESC	CRIPTION	9
	2.1	Site Setting	
	2.2	Topography	9
	2.3	Climatological Information	9
	2.4	Site Drainage	10
	2.5	National Pollutant Discharge Elimination System	10
		(NPDES) Outfalls	13
	2.6	Soils	15
	2.7	Site Hydrogeology	16
	2.7.1	Previous Investigation	16
	2.7.2		17
	2.7.3	Production Well Use	17
	2.7.4		
		2.7.4.1 Regional Geology	
		2.7.4.2 Site Geology	
	2.7.5	Groundwater	
		2.7.5.1 Occurrence of Groundwater	
		2.7.5.2 Subsurface Dissolution Features	
		2.7.5.3 Groundwater Flow	
		2.7.5.3a Groundwater Flow - Supplemental Data	252
		2.7.5.4 Continual Groundwater Level Monitoring	26
	2.7.6		
3.0	RECORD R	EVIEW	30
	3.1	Aerial Photography Review	30
	3.2	Interviews/Site History	31

= :

	3.3		Regulatory File Review	34
	3.4		Bethlehem Steel Corporation File Review	36
	3.5		Off-Site Well Inventory	37
			•	
4.0	SITE	E CHAR	ACTERIZATION	38
	4.1		Introduction	38
		4.1.1	Classification of Site Observations	39
	4.2		Environmental Sampling Methodologies	41
		4.2.1	Introduction	41
		4.2.2	Soil Sampling Nomenclature	41
		4.2.3	Soil Sampling	44
			4.2.3.1 Soil Sampling Locations	44
			4.2.3.2 Soil Screening Methods	45
			4.2.3.3 Soil Sampling Methods	46
		4.2.4	Quality Assurance/Quality Control Procedures	
		4.2.5	A	48
	4.3			49
		4.3.1		49
		4.3.2	Monitoring Well Drilling and Installation	50
		4.3.3	Decontamination Procedures	51
		4.3.4	Monitoring Well Construction	
		4.3.5	Well Surveying	52
		4.3.6	Well Development/Well Purging	52
		4.3.7	Groundwater Sampling	53
		4.3.8	Analytical Parameters and Methods	54
		4.3.9	Quality Assurance/Quality Control	54
		4.3.10	Geoprobe® Wells	55
	4.4		Field Reconnaissance	55
		4.4.1	Northwest Section of the Site	56
		4.4.1a	Northwest Section Supplemental Sample Results 5	
		4.4.2	Brass Foundry	
		4.4.3	T T .	
		4.4.4	Electroslag Refining (ESR)	
		4.4.5	C - C - A - C1	70
		4.4.6	Central Tool Annex, Central Tool Shop, and	, 0
			TT4 The state of	72
		4.4.6a	Central Tool Annex Supplemental Sample Results 7	
		4.4.7	Drop Forge	
		4.4.8	Pipe Shop	
		4.4.9	<b>**</b> 1	QA

		4.4.10	Electrical Repair Building	. 85
		4.4.10	Electric Repair Building Supplemental Sample Results	. 93a
		4.4.11	Pattern Storage and Carpenter and Pattern Shop	
		4.4.12	Paint House and Oil House	
		4.4.13	Medical Center	. 98
		4.4.14	General Sales Office	. 98
		4.4.15	Bethlehem Plant Office	. 99
		4.4.15a	Bethlehem Plant Office	. 99a
		4.4.16	"A," "B," "C," "D," and "E" Blast Furnaces	
		4.4.16a		
		4.4.17	Lehigh Power House	
		4.4.18	South Covered Tool Steel Yard	110
		4.4.19	Machine Shop No. 2	
		4.4.19a	Machine Shop No. 2 Supplemental Sample Results	114a
		4.4.20	Electric Furnace Melting (EFM) Department	115
		4.4.21	Steel Foundry	121
		4.4.22	Ore Yard and Car Tipper	
		4.4.23	Sintering Plant and Loop Substation	128
		4.4.24	PB & NE Railroad Locomotive Repair	130
		4.4.24a	PB & NE Building Supplemental Sample Results	132a
		4.4.25	Tempering, Weldment, and Boiler Houses	133
		4.4.26	Chemical and Physical Lab	140
		4.4.27	Car Tipper Substation	141
		4.4.28	Coke Gas Mains	142
		4.4.29	Underground Utilities	
		4.4.30a	Open Areas Supplemental Sample Results	143a
5.0	SOIL	GAS QU	J <b>ALITY</b>	144
	5.1a	Indoor A	Air Quality	145a
	5.2a	Modelir	ng Volatilization to Outdoor and Indoor Air	145b
6.0	GRO	UNDWA'	TER QUALITY	146
	6.1	N	Monitoring Well Results	146
		6.1.1	September 1995	148
		6.1.2	October 1995	149
		6.1.3	March 1997	149
		6.1.4	June 1997	149
		6.1.5	September 1997	150
		6.1.6	January 1998	151
	6.2	F	Former Water Supply Wells	152

	6.2	2.1a 2.2 2.2a	Spring Pit	152a 153
7.0	<b>RISK ASS</b> 7.1	Introd	NT	155 155
	7.2		sure Pathway Analysis	155
	7.2		Current Land Use	156
	7.2		Future Land Use	156
		2.3	Identification of Exposure Pathways	157
	7.3		onship to Surface Water Quality Criteria	158
	7.4		Calculated Groundwater Concentrations Protective of	
			ce Water Quality Standards	164
	7.5	Use of	f Groundwater	165
	7.6	Potent	tial Ecological Risks	166
8.0 9.0 10.0	LIMITAT	CIONS .	TUP PLANS	<ul><li>167</li><li>168</li><li>169</li></ul>
			List of Figures	
_			ap Following	
			Map and Sampling Locations Following	
_			per Month Following	
			Well Flow per Month Following	
			y Map Following	
			-A' Following	
_			charge Basin Following	
			-B' Following	
			-C' Following	
_			Contour Map, October 18, 1996 Following	
_			Contour Map, October 29, 1996 Following	
			Contour Map, December 18, 1996 Following	
			Contour Map, January 13, 1997 Following	

Figure 15, Groundwater Contour Map, June 3, 1997	Following Text
Figure 16, Groundwater Contour Map, September 24, 1997	Following Text
Figure 17, Groundwater Contour Map, January 28, 1998	
Figure 18, Continual Groundwater Elevation Plot -	· ·
Monitoring Well BF-4	Following Text
Figure 19, Continual Groundwater Elevation Plot -	•
Monitoring Well BF-5	Following Text
Figure 20, Continual Groundwater Elevation Plot -	
Monitoring Well BF-2	Following Text
Figure 21, Continual Groundwater Elevation Plot -	J
Monitoring Well BF-3	Following Text
Figure 22, Continual Groundwater Elevation Plot -	
Monitoring Well BF-9	Following Text
Figure 23, Approximate Locations of Chemical Storage Areas	Following Text
Figure 24, Approximate Locations of Degreasers	Following Text
Figure 25, Approximate Locations of Hydrocarbon Handling Areas	Following Text
Figure 26, Approximate Locations of Machine Shops	Following Text
Figure 27, Approximate Locations of Paint Areas	Following Text
Figure 28, Approximate Locations of Pits and Sumps	Following Text
Figure 29, Approximate Locations of Waste Handling Areas	Following Text
Figure 30, Approximate Locations of Tanks	Following Text
Figure 31, Approximate Locations of Other Concerns	Following Text
Figure 32, Northwest Area Approximate Test Pit Locations	Following Text
Figure 33 (Revised), Central Tool Annex Sample Locations	Following Text
Figure 34, Vapor Degreaser Containment Pit	Following Text
Figure 35 (Revised), Electrical Repair Sample Locations	Following Text
Figure 36 (Revised), Blast Furnace Repair Sample Locations	Following Text
Figure 37 (Revised), Machine Shop No. 2 Sample Locations	Following Text
Figure 38, Sintering Plant Sample Locations	Following Text
List of Tables	
Table 1, Monitoring Well Construction Data Summary	Following Text
Table 2, Stratigraphic Column	Following Text
Table 3, Aquifer Recharge Rates	Following Text
Table 4, Groundwater Flow Estimate	Following Text
Table 5, Static Water Levels	
Table 5A, Additional Static Water Levels	
Table 6, Daily Precipitation Summary (October 1996 to	_
January 1997)	Following Text

Table 7, Off-site Well Inventory	Following	Text
Table 8, Northwest Section FID/PID Results, Analytical		
Parameters, and Subsurface Descriptions	Following	Text
Table 9 (Revised), Northwest Section Soil Sample Analytical Results .	Following	Text
Table 10 (Revised), Northwest Section Summary of Analytical Results	•	
And Comparison to MSCs	Following	Text
Table 11, TP-5, Tar Pit Solid and Soil Sample Analytical Results	_	
and Comparison to MSCs	Following	Text
Table 12, WHA #60B,C,E Analytical Parameters and Subsurface		
Descriptions		
Table 13, WHA #60B,C,E Soil Sample Analytical Results	Following	Text
Table 14, WHA #60B,C,E Summary of Analytical Results and		
Comparison to MSCs	Following	Text
Table 15, Iron Foundry Oil House Analytical Parameters and		
Subsurface Descriptions	Following	Text
Table 16, Iron Foundry Oil House Soil Sample Analytical Results	Following	Text
Table 17, Iron Foundry Oil House Summary of Analytical Results		
and Comparison to MSCs	Following	Text
Table 18, ESR Lead Babbitting Area (O-38) Analytical Parameters		
and Subsurface Descriptions	Following '	Text
Table 19, ESR Lead Babbitting Area (O-38) Soil Sample		
Analytical Results	Following '	Text
Table 20, ESR Lead Babbitting Area (O-38) Summary of Analytical	_	
Results and Comparison to MSCs	Following '	Text
Table 21, West of Central Tool Annex FID/PID Results, Analytical		
Parameters, and Subsurface Descriptions	Following '	Text
Table 22, West of Central Tool Annex Field GC Results	Following '	Text
Table 23, West of Central Tool Annex Soil Sample Analytical	_	
Results	Following '	Text
Table 24, West of Central Tool Annex Summary of Analytical		
Results and Comparison to MSCs	Following '	Text
Table 25, East of Heat Treatment and Central Tool Shop Analytical		
Parameters and Subsurface Descriptions	Following '	Text
Table 26, East of Heat Treatment and Central Tool Shop Soil		
Sample Analytical Results	Following '	Text
Table 27, East of Heat Treatment and Central Tool Shop Summary		
of Analytical Results and Comparison to MSCs	Following '	Text
Table 28, Central Tool Annex FID/PID Results, Analytical		
Parameters, and Subsurface Descriptions	Following '	Text

= :

Table 29, Central Tool Annex Field GC Results	Following Text
Table 29A, Central Tool Annex Soil Gas Results	
Table 29B, Central Tool Annex Summary of Analytical Results and	C
Comparison to Available Criteria	Following Text
Table 30 (Revised), Central Tool Annex Soil Sample Analytical	I one wing Toke
Results	Following Text
Table 31 (Revised), Central Tool Annex Summary of Analytical Results	Tollowing Text
and Comparison to MSCs	
Table 31A, Central Tool Annex Groundwater Sample Analytical	rollowing Text
	Callerring Tank
Results	Following Text
	<b>.</b>
Analytical Results and Comparison to MSCs	Following Text
Table 32, Heat Treatment FID/PID Results, Analytical	
Parameters, and Subsurface Descriptions	Following Text
Table 33, Heat Treatment Soil Sample Analytical Results	Following Text
Table 34, Heat Treatment Summary of Analytical Results and	
Comparison to MSCs	Following Text
Table 35, Electrical Repair Soil Sample Analytical Results	Following Text
Table 36, Electrical Repair Summary of Analytical Results for	
Soils and Comparison to MSCs	Following Text
Table 37 (Revised), Electrical Repair Geoprobe Groundwater Sample	Following Text
Analytical Results	Following Text
Table 38 (Revised), Electrical Repair Summary of Analytical Results for	r
Groundwater and Comparison to MSCs	Following Text
Table 39, Electrical Repair FID/PID Results, Analytical	1 onowing Text
Parameters, and Subsurface Descriptions	Following Text
Table 40, Electrical Repair Field GC Results	Following Text
Table 41, Electric Repair Soil Sample Analytical Results	Following Text
Table 42, Electric Repair Summary of Analytical Results	ronowing text
	T-11
and Comparison to Available Criteria	rollowing lext
Table 43, Paint and Oil House FID/PID Results, Analytical	
	T-11 m 4
Parameters, and Subsurface Descriptions	Following Text
Table 44, Paint and Oil House Field GC Results	
Table 45, Paint and Oil House Soil Sample Analytical Results	rollowing Text
Table 46, Paint and Oil House Summary of Analytical Results	
and Comparison to MSCs	Following Text
Table 47, Blast Furnaces (A, B, C, D, E) Analytical Parameters	
and Subsurface Descriptions	Following Text

Table 48 (Revised), Blast Furnaces (A, B, C, D, E) Soil Sample	
Analytical Results	Following Text
Analytical Results and Comparison to MSCs	Following Text
Table 50 (Revised), Blast Furnace Storage FID/PID Results,	
Analytical Parameters, and Subsurface Descriptions	Following Text
Table 51, Blast Furnace Storage Field GC Results	Following Text
Table 52, Blast Furnace Storage Soil Sample Analytical Results Table 53, Blast Furnace Storage Summary of Analytical Results	Following Text
and Comparison to MSCs	Fallessin - T
Table 54, Blast Furnace Coke Drip Leg Analytical Parameters	rollowing lext
and Subsurface Descriptions	Following Text
Table 55, Blast Furnace Coke Drip Leg Soil Sample Analytical	Tollowing Text
Results	Following Text
Table 56, Blast Furnace Coke Drip Leg Summary of Analytical	_
Results and Comparison to MSCs	Following Text
Table 57, Blast Furnace Repair FID/PID Results, Analytical	
Parameters, and Subsurface Descriptions	Following Text
Table 58, Blast Furnace Repair Field GC Results	Following Text
Results	Fellowing Tour
Table 60 (Revised), Blast Furnace Repair Summary of Analytical	ronowing lext
Results and Comparison to MSCs	Following Text
Table 60A, Blast Furnace Repair Groundwater Sample Analytical	Tollowing Text
Results	Following Text
Table 60B, Blast Furnace Repair Summary of Groundwater	_
Analytical Results and Comparison to MSCs	Following Text
Table 61, Blast Furnace Repair Coal Tar Tank FID/PID Results,	
Analytical Parameters, and Subsurface Descriptions	Following Text
Table 62, Blast Furnace Repair Coal Tar Tank Field GC Results	Following Text
Table 63, Blast Furnace Repair Coal Tar Tank Soil Sample	T3 11
Analytical Results	Following Text
Analytical Results and Comparison to MSCs	Following Taxt
Table 65, Lehigh Power House FID/PID Results, Analytical	ronowing text
Parameters, and Subsurface Descriptions	Following Text
Table 66, Machine Shop No. 2 FID/PID Results, Analytical	
Parameters, and Subsurface Descriptions	Following Text
Table 67, Machine Shop No. 2 Field GC Results	Following Text

Table 68 (Revised), Machine Shop No. 2 Soil Sample Analytical	
Results	Following Text
Results and Comparison to MSCs	Following Text
Table 69A, Machine Shop No. 2 Geoprobe Groundwater Samples	
Table 69B, Machine Shop No. 2 Summary of Analytical Results	_
and Comparison to MSCs	Following Text
Table 70, EFM Baghouse Soil Sample Analytical Parameters and	
Subsurface Descriptions	Following Text
Comparison to MSCs	Following Text
Table 72, Southwest of EFM Storage Analytical Parameters and	1 onowing Text
Subsurface Descriptions	Following Text
Table 73, Southwest of EFM Storage Soil Sample	_
Analytical Results	Following Text
Table 74, Southwest of EFM Storage Summary of	
Analytical Results and Comparison to MSCs	Following Text
Table 75, West of EFM Storage Analytical Parameters and	Eallanning Tout
Subsurface Descriptions	Following Text
Table 77, West of EFM Storage Summary of Analytical Results and	ronowing text
Comparison to MSCs	Following Text
Table 78, Northwest Corner of EFM FID/PID Results, Analytical	
Parameters, and Subsurface Descriptions	
Table 79, Northwest Corner of EFM Field GC Results	Following Text
Table 80, Northwest Corner of EFM Soil Sample	
Analytical Results	Following Text
Table 81, Northwest Corner of EFM Summary of Analytical	E.u. : m
Results and Comparison to MSCs	Following Text
Analytical Parameters, and Subsurface Descriptions	Following Text
Table 83, Steel Foundry Drip Leg Analytical Parameters and	Tollowing Text
Subsurface Descriptions	Following Text
Table 84, Car Tipper FID/PID Results,	<b>3</b> - 1 11
Analytical Parameters, and Subsurface Descriptions	Following Text
Table 85, Car Tipper Field GC Results	Following Text
Table 86, Car Tipper Soil Sample Analytical Results	Following Text
Table 87, Car Tipper Summary of Analytical Results and	<b>.</b>
Comparison to MSCs	Following Text

**=** :

Table 88, Sintering Plant Analytical Parameters and
Subsurface Descriptions Following Text
Table 89 (Revised), Sintering Plant Soil Sample Analytical Results Following Text
Table 90 (Revised), Sintering Plant Summary of Analytical Results
and Comparison to MSCs Following Text
Table 91, PB&NE Building FID/PID Results, Analytical
Parameters, and Subsurface Descriptions Following Text
Table 92, PB&NE Building Field GC Results Following Text
Table 93, PB&NE Building Soil Sample Analytical Results Following Text
Table 94, PB&NE Building Summary of Analytical Results and
Comparison to MSCs Following Text
Table 95, North of Tempering No. 2 FID/PID Results,
Analytical Parameters, and Subsurface Descriptions Following Text
Table 96, North of Tempering No. 2 Soil Sample
Analytical Results Following Text
Table 97, North of Tempering No. 2 Summary of
Analytical Results and Comparison to MSCs Following Text
Table 98, Northeast of Weldment FID/PID Results, Analytical
Parameters, and Subsurface Descriptions Following Text
Table 99, Northeast of Weldment Field GC Results Following Text
Table 100, Northeast of Weldment Soil Sample
Analytical Results Following Text
Table 101, Northeast of Weldment Summary of Analytical
Results and Comparison to MSCs Following Text
Table 102, East of Tempering No. 3 Analytical Parameters
and Subsurface Descriptions Following Text
Table 103, East of Tempering No. 3 Soil Sample
Analytical Results Following Text
Table 104, East of Tempering No. 3 Summary of Analytical
Results and Comparison to MSCs Following Text
Table 104A, Open Areas Soil Sample Analytical Results Following Text
Table 104B, Open Areas Summary of Analytical Results
and Comparison to MSC Following Text
Table 105, Field GC Results (April and July 1997) Comparison
to Standards Following Text
Table 106, Summary of Analytical Results for Groundwater -
September 1995 Following Text
Table 107, Summary of Analytical Results for Groundwater -
October 1995 Following Text
control 1995

Table 108 St	ummary of Analytical Results for Groundwater -	
March 1997 Following Text		
Table 109, Summary of Analytical Results for Groundwater -		
	une 1997 Following Text	
Table 110, Su	ummary of Analytical Results for Groundwater -	
S	eptember 1997 Following Text	
	ummary of Analytical Results for Groundwater -	
J:	anuary 1998 Following Text	
	entification and Evaluation of Exposure Pathways Following Text	
	valuation of Surface Water Quality Criteria Following Text	
	erivation of Groundwater Concentrations that are	
Р	rotective of Surface Water Quality Following Text	
	List of Appendices	
Appendix A,	Notice of Intent to Remediate and Act 2 Correspondence Letters	
Appendix B,		
	Stage Elevation Difference: USGS and Pump House Intake	
	Computer-Assisted File Review	
Appendix E,	Spill History	
	Off-Site Well Inventory	
	Waste Handling Area Descriptions	
	UST Documentation	
Appendix I,	Well Construction and Boring Logs	
Appendix J,	Supplemental Evaluation of Environmental Conditions in the Vicinity of the	
	Electric Repair Building	
Appendix K,	Derivation of Groundwater Discharge to the Lehigh River	
Appendix L,	Derivation of Dilution Factors for Calculating In-Stream Concentrations	
	Using Mass Balance Techniques Based on the Partial Mix Factor (Yc)	
Appendix M,	Generic Cleanup Plans	
Appendix N,	Procedure to Use Clean Fill On-Site	
Appendix O,	Derivation of Risk-Based Screening Levels for Groundwater Volatilization	
	to Outdoor and Indoor Air Based on the RBCA Spreadsheet System Model	
	List of Plates	
Plate 1, Prope	rty Description	
Volume 2 T	shamatawa Awalasia Danasta	
Volume 2 - Laboratory Analysis Reports Volume 3 - Laboratory Analysis Reports for Supplemental Samples		